SELECTED EXAMPLES OF VHF SIGNAL PROPAGATION CONTRACT DA 36-039 AMC-00040(E) ORDER NO. 5384-PM-63-91 DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED RECORDS IN TROPICAL TERRAINS E. M. KREINBERG U.S. ARMY ELECTRONICS COMMAND FORT MONMOUTH, NEW JERSEY 07703 Special Technical Report 35 By: N. K. SHRAUGER Prepored for:

SELECTED EXAMPLES OF VHF SIGNAL PROPAGATIO.

By: N. K. SHRAUGER E. M. KREINBERG

Prepared for:

U.S. ARMY ELECTRONICS COMMAND FORT MONMOUTH, NEW JERSEY 07703

CONTRACT DA 36-039 AMC-00040(E) ORDER NO. 5384-PM-63-91

SRI Project 4240

Distribution of this focument is unlimited.

Approved: E. L. YOUNKER, TECHNICAL DIRECTOR MRDC Electronics Labarotary, Bangkok

W. R. VINCENT, MANAGER Cammunication Lobarotary D. R. SCHEUCH, EXECUTIVE DIRECTOR Electronics and Rodia Sciences Sponsored by
ADVANCED RESEARCH PROJECTS AGENCY
ARPA Order 371

Slow-speed chart records of received signal strength showing
the perturbations caused by scattering from trees in the VHF band
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations,
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations, and bamboo. The records permit a qualitative evaluation of the
the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations, and bamboo. The records permit a qualitative evaluation of the magnitude of signal fading that is superimposed upon the smooth
are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations, and bamboo. The records permit a qualitative evaluation of the magnitude of signal fading that is superimposed upon the smooth decrease of received signals with distance between transmitter
are presented. Data for several frequencies and polarizations of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations, and bamboo. The records permit a qualitative evaluation of the magnitude of signal fading that is superimposed upon the smooth decrease of received signals with distance between transmitter and receiver. Some similar results are presented for an AN/PRC-2

BSTRACT .			1 i
IST OF IL	ILLUSTRATIONS		÷ † ÷
INTRO	INTRODUCTION		~:
II TEST	DESCRIPTION		7
Α.	Xeledop System		7
B.	AN/PRC-25		7
II TERR/	TERRAIN DESCRIPTIONS	•	က
Α.	Tropical Rain Forest		က
ъ.	Rubber Plantation	•	7
ပ်	Bamboo		10
EXAMI	EXAMPLES		15
Α.	Tropical Rain Forest		16
B.	Rubber Plantation		91
ပ်	Ватьо		1:
EFERENCES			36
ISTRIBUTION	ON LIST		37
Form 1475	213		

ILLUSTRATIONS

24

	ILLUSTRATIONS	Fig.	20	AN/PRC-25 Along Trail A; Receiver in Forest (Point C) Using 10-foot Whip Antennas (AT-271/PRC)Undergrowth between 0.1 and 0.25 Mile Removed	Ň
Fig. 1	Manpack Xeledop In Horizontally-Polarized Position	Fig.	21	Boundary Effect: Xeledop Along Trail A; Unbal- anced Receiving Antennas in Clearing (Point A);	
Fig. 2	Air View of Chumphon Test Area	4			8
Fig. 3	Forest and Undergrowth at Chumphon Test Area	5 Fig.	22	p Along Trail A; Unbal	
Fig. 4	Trail A Through Chumphon Test Area	9		anced Receiving Autennas in Clearing (Foint A); Vertical Polarization	Ñ
Fig. 5	Manpack Xeledcp Testing at Chumphon Site (Trail A)	7 Fig.	23	Boundary Effect: Expanded-Scale Version of	
Fig. 6	Plan View of Rain Forest Test Site (Chumphon)	· •			Ò
Fig. 7	Aerial View of Trail R-1 Showing Clearing and Rubber Plantation	Fig.	24	Xeledop Along Trail B: Receiving Antennas in Forest (Point E); Horizontal Polarization 2	ลั
Fig. 8	Interior View of Rubber Plantation (Trail R-1) 10	Fig.	25		Č.
Fig. 9	Plan View of Rubber Plantation Test Site (Chumphon)	Fig.	26	Along Trail B; Receiving Antennas in	i č
Fig. 10	Clearing and Plantation Boundary of Trail R-1 (Rubber)	Fig.	27	long Trail B; Receiving Antennas in	, ,
Fig. 11	Interior View Along Trail R-2 (Rubber) 13		Ċ	(FOINC D), VELLICAL FOIALISALION	כ
Fig. 12	Bamboo Test Site (Chantaburi)14	- X0 -1 -4	7	lanced Receiving Antennas in Clearing (Point A,	
Fig. 13	Plan View of Bamboo Test Site (Chantaburn) 15			Fig. 9); Vertical Polarization 3	က
Fig. 14	Vertical Polarization: Xeledop Along Trail A; Receiving Antennas in Clearing (Point B) 18	Fig.	29	<pre>1 R-1 (Rubber) aring (Point A,</pre>	ě
Fig. 15	Horizontal-to-Vertical Polarization: Xeledop Along Trail A; Receiving Antennas in Clearing (Point B)	F.	30	cal Polarization: Xeledop Along Trail R-2 per); keceiving Antennas in Forest (Point D,	j 6
Fig. 16	Horizontal Polarization: Xeledop Along Trail A; Receiving Antennas in Clearing (Point B) 20	Fig.	31	contai Polarization: Xeledop Along Trail R-2)
Fig. 17	Vertical-to-Horizontal Polarization: Xeledop Along Trail A; Receiving Antennas in Clearing (Point B)	다 야	32	ong Bamboo;	က်
g. 18	Signals Received in a Clearing (Point B) Compared With Signals Received in a Forest (Point C) as Xeledop was Carried Along Trail A	F1 8	33	Receiving Antennas in Bamboo (see Fig. 13)	ෆ්
Fig. 19	AN/PRC-25 Along Trail A; Receiver in Fures: (Point C) Using 10-foot Whip Antennas (AT-271/PRC) 23	_			

test method, and the results obtained from early studies. Similar tests were made at Chumphon using an ...N/PRC-25 manpack system with this report were selected from a large number of records that were These selected records permit mitting elementary dipole with optional polarization) is described communication in a tropical environment. A recent phase of this A major effort by Stanford Research Institute under Project signals at several frequencies and polarizations, and at low an-AT-271/PRC intennas (10-foot whips). The examples presented in nution with distance for open and forested terrains and various tenna heights. The technique using the manpack Xeledop (transa qualitative evaluation of the signal fading and rate of dimiwhich discusses the made during an extensive measurement program near the towns of SEACORE is directed toward solving problems of manpack radio effort is to document the effects of terrain on received VHF in detail in a Special Technical Report, $^{\mathrm{l}}$ frequencies and antenna polarizations Chumphon and Chancaburi, Thailand.

A. Xeledop System

was developed for use in measuring the radiation patterns of fullmulticoupler circuit, transmitting at a power of 1/3 watt on each 75.1, and The Xeledop The unit is designed to transmit CW signals on three output, and its elementary dipole radiation pattern when in free I dB and that the frequency drift is negligible over a period of 100 MHz. The simultaneous CW transmissions were used to obtain The tests described in this report were carried out with a Xeledop transmitter are its stable frequency and constant power Tests have shown that the power cutput varies less than eight hours. The Xeledop incorporates three crystal-controlled transmitters that are coupled to the dipole antenna through The chief characteristics frequencies simultaneously or in pulsed sequence on 50, technique based on the use of a Xeledop transmitter. the data presented in this report. scale HF and VHF antennas.²,3 frequency. space.

The VHF Xeledop is small enough to be carried on a back pack, at shown in Fig. 1. The experiment consists of having a man carry the Xeledop along a surveyed trail (which is marked at intervals corresponding to the radial distances from the receiving antenna) and recording the signal strength at the receiver position. The receiving end of the system consists of stable receivers (R-390s with crystal-controlled converters) fed with unbalanced, resonant half-wave dipole antennas. The feed point of these antennas was placed 10 feet above ground. The converter input was padded to 50 ohms with a 10 dB series attenuator and the resulting minimum usable signal was -110 dBm. The receivers have provisions for obtaining an output that can be directly related to the received

References are listed at the end of the report.

Chumphon is located in southern Thailand on the Malay Peninsula near the Isthmus of Kra. Chantaburi is in southeast Thailand on the coast near the Cambodian border.



FIG. 1 MANPACK XELEDOP
IN HORIZONTALLY—
POLARIZED POSITION

chan: I paper-strip-thart recorder to which a callibration of signal strength is added. Up to four signals having different frequencies or polarizations can be simultaneously recorded with this set-up. As the Xeledop transmitter is moved along the trail, a second man carrying a small hand-held transceiver walks several wavelengths ahead of the transmitter. His job is to re. y to the recorder operator the transmitter's position as it is carried past each of the radius markers. These distances are marked on the chart record of the received signal strength by the receivingsite operator. (A chart speed of 1 mm/sec was used.) Thus, the experimental results are obtained as a calibrated, paper-chart recording of received signal vs. radial distance. The calibration of signal strength is in dB above 0.7 µV across the 50-ohm receiver input for all records except the AN/PHC-25 data where the reference voltage was 2.2 µV across 50 ohms (see Sec. II-B).

signal strength. This output is continuously recorded on a 4-

The Xeledop measurements were conducted over several trails and terrains for 50, 75.1, and 100 MHz. Four polarization combinations were used: V-V, H-V, V-H, and H-H. (The first letter refers to the Xeledop transmitter, the second to the receiving antenna.)

B. AN/PRC-25

Some data runs were conducted in the rain forest site (Chumphon) using AN/PRC-25 radio sets equipped with 10-foot-long whip antennas (AT-271/PRC). An AN/PRC-25 transmitter was carried

The trails were surveyed and marked in units of radial range. In cases where the trails were rot linear, or where the man carrying the Xeledop did not walk with constant speed, the absissa (distance scale) on these records was not precisely linear. Nevertheless, the distances marked on the chart record were radial ranges, and the distance scale is approximately linear for the example records presented in this report.

An AN/PRC-25 set with its receiver modified for recording the signal variations appearing at the emitter of the fourth limiter stage was used at the receiving terminal. Received signal-versusdistance records comparable to Xeledop records were thus obtained. The radio sets were supplied by 12 V, 30 amp-hour motorcycle batteries to ensure constant dc input power during the trials. Details of this instrumentation are given in Ref. 4.

III TERRAIN DESCRIPTIONS

A. Tropical Rain Forest

Most of the records in this report are taken in a fresh-water tropical rain forest on the Malay peninsula near Chumphon, Thailand, a few hundred miles south of Bangkok. There, trees are very numerous, having straight boles (trunks) and a rather dense, uniform canopy (Fig. 2). The forest has a mean height of 12 meters, and 90% of the trees are less than 27 meters high. Most of the forest area is covered with an undergrowth of broad-leaf and thorny plants that is about 2 to 3 meters in height and easily removed by cutting (Fig. 3).

The forest floor is very wet, usually covered with 3 to 10 inches of water. This standing water necessitated the construction of board walks to allow carrying the transmitters at a fairly constant pace (Figs. 4 and 5).

Figure 6 is a diagram of the forest and terrain along the two trails that were used in this investigation. The number and size of trees along Trail A were reasonably uniform. At the beginning of the tests, undergrowth immediately bordering Trail A was cut for about the first 0.1 mile into the forest. Later, the underbrush along Trail A was removed for about 100 feet either side of the trail and a distance of 0.25 mile into the forest.

This clearing of the undergrowth was done in order to determine whether the Xeledop tests could differentiate between the presence and absence of undergrowth. Trail B was chosen to lie along the edge of the boundary between large trees and existing undergrowth.

A detailed report on foliage nd soil characteristics is in preparation. The electrical properties of the ground and vegetation at this site are documented in Ref. 6.



FIG. 2 AIR VIEW OF CHUMPHON TEST AREA



FIG. 3 FOREST AND UNDERGROWTH AT CHUMPHON TEST AREA




FIG. 4 TRAIL A THROUGH CHUMPHON TEST AREA



FIG. 5 MANPACK XELEDOP TESTING AT CHUMPHON SITE (Trai! A)

As one can note from Fig. 6, this trai' passes a few large trees at the beginning, goes through an area of undergrowth only, there passes through a section of large trees, proceeds through a portion with larg. trees on one side and underbrush on the other, goes through a relatively long portion with large trees on both sides, and then passes through the center of a small clearing. Thus, a variety of large tree/underbrush combinations was obtained along frail B.

B. Rubber Plantation

Several test records in this report were taken in a mature, undergrowth-free rubber plantation located near Chantaburi in southeastern Thailand. The trees in this plantation were of uniform height (Fig. 7) and were growing in rather uniform rows (Fig. 8). The trees hai a separation between rows and columns of about 3 meters, and an average diameter (1.3 meters above ground) of 24 cm. The height of plantation trees averaged 18 to 20 meters.

Keledop tests were conducted along the two trails sbown in fig. 9, a plan-view sketch of this ite. Trail R-1 was laid through both clearing and rubber trees. The Keledop was carried from the receiving antennas located at Point A, across the clearing and into the forest (Point B). The runs then continued along the centerline between two rows of trees inside the forest, stopping at Point C. Figure 10 shows the clearing and boundary portions of Trail R-1, while Fig. 8 is an interior view of the plantation portion of this trail. In order to present a sharp boundary to the Xeledop, small bushes and trees were removed for 100 feet on either side of the test trail.

rail R-2 lies entirely inside the rubber plantation. The receiving antennas (and the start of the Xeledop runs) were located at Point D (Fig. 9). The first portion of this trail was in an



FIG. 7 AERIAL VIEW OF TRAIL R-1 SHOWING CLEARING AND RUBBER PLANTATION




FIG. 8 INTERIOR VIEW OF RUBBER PLANTATION (Trail R-1)

area that had not been used for some time and in which the undergrowth had become quite heavy. This undergrowth was cut (and left to die) for 100 feet on either side of the trail. The undergrowth cut to make the trail itself was removed to either side. Figure 11 is a veiw of Trail R-2. Again the Xeledop was carried on a line centered between two rows of trees. Trail R-2 was only straight in segments, however (see Fig. 9), since the trees were in rows according to small plots owned by individual families.

3. Bemboo

A brief experiment was conducted to determine effects of bamboo foliage on VHF propagation. The bamboo test site, also near Chantaburi, was in an area containing large patches of bamboo intermixed with marshy clearings and rice paddy fields (Fig. 12). The bamboo was about 4 to 6 meters in height and very dense. ground was very wet at the time of the measurements; in fact, 10 days before the measurements the ground was 6 to 8 inches under water. Thus, this foliage can be classified as "wet bamboo."

The test trail, although short, was such that the Xeledop signals traveled through a nearly continuous patch of bamboo. Figure 13 is a plan view of the site. The receiving antennas were immersed in the bamboo at a convenient location. Because there was not time to obtain permission to cut a test trail through the foliage, the test trail was located along a canal that crossed through the site. The starting point (A) for Xeledop runs was 0.07 mile from the receiving antennas. The Xeledop was carried along the edge of the foliage such that an ever-increasingly direct path through the bamboo existed between the Xeledop and the receiving antennas.




FIG. 9 PLAN VIEW OF RUBBER PLANTATION TEST SITE (Chantaburi)




FIG. 10 CLEARING AND PLANTATION BOUNDARY OF TRAIL R-1 (Rubber)



FIG. 11 INTERIOR VIEW ALONG TRAIL R-2 (Rubber)



FIG. 12 BAMBOO TEST SITE (Chantaburi)




FIG. 13 PLAN VIEW OF BAMBOO TEST SITE (Chantaburi)

grouped at the end of the text. At the top of Fig. 14 schematically and a distance scale between the receiving antennas scale and also by the capital letter in parentheses in the figure Location of the receiving antennas is indicated on each distance through 27 is a reproduction of the actual chart recording made traces are shown for 50, 75, and 100 MHz. Below the recordings structure of the terrains where the test runs were carried out. The variation of signal strength with distance for a wide and points along the test trail is given. The sketches of the title (e.g., Point B). The test geometry may be identified by during the Xeledop or AN/PRC-25 runs. In most cases separate foliage are typical but do not indicate more than the general variety of conditions and three terrains is shown in Fig. on Fig. 14 through 27, the nature of the terrain is shown reference to the site maps (Figs. 6, 9, and 13). through 33,

Two comments concerning interpretation of these data should be noted. First of all, these records are presentations of the raw data. Antenna efficiencies and cable losses have not been accounted for. Thus, the records should not be used to make frequency comparisons of the magnitude of the received signal. Second, examination of Figs. 14 through 33 shows many of the signal traces reaching and remaining at 0 dB over the latter portions of the test runs. The reason for this is that the lower end of the dynamic range of measurement has been reached. (All receivers were calibrated for the same 0-dB reference.)

Detailed comparisons of medians in terms of frequency, polarization, or other parameters can be found for tropical rain forest in Ref. 4.

A. Tropical Rain Forest

the receiving antenna upon the received signal. The four recordings the receiving antennas were placed about 50 feet inside the clearing to the received signal strength, and the transmitting AN/PRC-25 was addition to illustrating the effect of scattering of trees upon the cation of the effect of removing underbrush along the trail between modified to permit the recording of a voltage that was proportional horizontal, and two cases of crossed polarization. For these runs runs on Trail A in the rain forest near Chumphon (Figs, 14 through 27). Figures 1.4 through 17 show the variation of signal strength ments made with two AN/PRC-25 VHF manpack radics in an experiment similar to the manpack Xeledop runs. The receiving AN/PRC-25 was signal received by the AN/PRC-25, Figs. 19 and 20 give some indiantenna about 50 feet outside and two antennas about 50 feet inof the examples in this report were taken from Xeledop In shown in this figure were made simultaneously with two receiving side the forest. Figures 19 and 20 show the results of measurefrom the forest boundary. Figure 18 illustrates, for horizontal the 0.1 and 0.25 mile markers. It is difficult to discern much, polarization and two frequencies, the effect of foliage around but with the underbrush removed (Fig. 20), the fading appears at three frequencies for vertical-to-vertical, horizontal-tocarried along the trail in the conventional manpack manner. somewhat less severe

The AN/PRC-25 records show the effect of maximum limiting for the first part of the trail, where the distance between transmitter and receiver is so small (i.e., the received signal is so large) that the set is fully limited. Variations of this voltage do not begin until a distance of about 0.05 mile is reached. This effect could be eliminated by inserting an attenuator between the antenna and the first stage of the receiver, but this was not judged to be necessary for the purposes of these tests.

Figures 21 and 22 illustrate the marked perturbation in the received VHF signal when the receiving antennas are well in the clear and the transmitter approaches the boundary of the forest. For these runs the receiving antennas were placed 0.15 mile from the forest boundary and the Xeledop transmitter was carried on a straight line twoard the boundary, starting at the receiving antennas, passing the forest-clearing interface, and continuing nearly one-half mile inside the forest. A considerably larger boundary effect was observed for horizontal polarization than for vertical. Figure 23 is an expanded distance scale version of Fig. 21, to show the boundary effect for horizontal polarization in more detail.

Figures 24 through 27 show the results of Xeledop measurements along Trail B, which intersects several clearings that are separated by portions of the forest. The schematic drawings of trees and undergrowth shown at the bottom in these figures correspond approximately to the groupings of vegetation along Trail B (plan shown in Fig. 6). In general, in the signal records it was impossible to effectively differentiate between presence and absence of undergrowth along those portions of the trail having large trees. There are indications on some of the records (e.g., 50 MHz, Fig. 25, 100 MHz, Fig. 26) that signal strength increased where there were no large trees (0.25 to 0.30 mile on Trail B), but more data would be required to document such a recovery effect.

B. Rubber Plantation


The test runs at the rubber plantation site provided an opportunity to observe the effect of a rather regular matrix (Figs. 8 and 11) of trees on the received signals. These runs also provided information about the effect of a sharp, regular plantation-clearing interface on the signals.

Four figures are presented to show the rubber plantation results. Figures 28 and 29 give the boundary effect as the Xeledop is carried from the clearing toward and into the plantation. Receiving antennas were located at Point A of Fig. 9. The other two figures (30 and 31) show the signal perturbations experienced as the Xeledop is carried over a longer trail entirely within the plantation. The receiving antennas were located in the forest as well.

C. Bamboo

Two examples of VHF signal propagation through bamboo are given in Figs. 32 and 33. The antennas were located inside the bamboo, but because of the nature of the trail, the starting point for the Xeledop was further down the trail (see Fig. 13). Thus, in these figures, the signal trace begins at 0.07 mile from the receiving antennas.

The bamboo contained no large stems. Thus, signal fluctuation, as expected, was very small compared to that in the rain forest or rubber plantation results.






FIG. 14 VERTICAL POLARIZATION: XELEDOP ALONG TRAIL A; RECEIVING ANTENNAS IN CLEARING (Point B)




FIG. 15 HORIZONTAL-TO-VERTICAL POLARIZATION: XELEDOP ALONG TRAIL A; RECEIVING ANTENNAS IN CLEAPING (Point B)




FIG. 16 HORIZONTAL POLARIZATION: XELEDOP ALONG TRAIL A; RECEIVING ANTENNAS IN CLEARING (Point B)




FIG. 17 VERTICAL-TO-HORIZONTAL POLARIZATION: XELEDOP ALONG TRAIL A; RECEIVING ANTENNAS IN CLEARING (Point B)




FIG. 18 SIGNALS RECEIVED IN A CLEARING (Point B) COMPARED WITH SIGNALS RECEIVED IN A FOREST (Point C) AS XELEDOP WAS CARRIED ALONG TRAIL A






FIG. 19 AN/PRC-25 ALONG TKAIL A; RECEIVER IN FOREST (Point C) USING 16-FOOT WHIP ANTENNAS (AT-271/7RC)



AN/PRC-25 ALONG TRAIL A; RECEIVER IN FOREST (Point C) USING 10-FOOT ALIP ANTENNAS (AT-271/PRC) --- UNDERGROWTH BETWEEN 0.1 AND 0.25 MILES REMOVED FIG. 20



BOUNDARY EFFECT: XELEDOP ALONG TRAIL A; UNBALANCED RECEIVING ANTENNAS IN CLEARING (Point A); HORIZONTAL POLARIZATION FIG. 21




FIG. 22 BOUNDARY EFFECT: XELEDOP ALONG TRAIL A; UNBALAMCED RECEIVING ANTENNAS IN CLEARING (Point A); VERTICAL POLARIZATION




FIG. 23 BOUNDARY EFFECT: EXPANDED-SCALE VERSION OF FIG. 21




FIG. 24 XELEDOP ALONG TRAIL B; RECEIVING ANTENNAS IN FOREST (Point E); HORIZONTAL POLARIZATION




FIG. 25 XELEDOP ALONG TRAIL B; RECEIVING ANTENNAS IN FOREST (Point E); VERTICAL POLARIZATION




FIG. 26 XELEDOP ALONG TRAIL B; RECEIVING ANTENNAS IN CLEARING (Point D); HORIZONTAL POLARIZATION




FIG. 27 XELEDOP ALONG TRAIL B; RECEIVING ANTENNAS IN CLEARING (Point D); VERTICAL POLARIZATION




FIG. 28 BOUNDARY EFFECT: XELEDOP ALONG TRAIL R-1 (Rubber)
UNBALANCED RECEIVING ANTENNAS IN CLEARING
(Point A, Fig. 9); VERTICAL POLARIZATION




FIG. 29 BOUNDARY EFFL_T: XELEDOP ALONG TRAIL R-1 (Rubber); UNBALANCED RECEIVING ANTENNAS IN CLEARING (Point A, Fij. 9); HORIZONTAL PGLARIZATION




FIG. 30 VERTICAL POLARIZATION: XELEDOP ALONG TRAIL R-2 (Rubber); RECEIVING ANTENNAS IN FOREST (Point D, Fig. 9)




FIG. 31 HORIZONTAL POLARIZATION: XELEDOP ALONG TRAIL R-2 (Rubber); RECEIVING ANTENNAS IN FOREST (Point D, Fig. 9)





FIG. 32 VERTICAL POLARIZATION: XELEDOP ALONG BAMBOO; RECEIVING ANTENNAS IN BAMBOO (See Fig. 13)



REFERENCES

- 1. N. K. Shrauger a. J K. L. Taylor, "Initial VHF Propagation Results Using Xeledop Techniques and Low Antenna Heights," Special Fechnical Report 26, Contract DA 36-039 AMC-00040(E), SRI Project 4240, Stanford Research Institute, Menlo Park, California (December 1966).
- C. Barnes, "Transmitters Towed Through Air Test Antenna's Radiation Pattern," Electronics, pp. 96-101 (18 October 1965).
- 3. G. H. Hagn, et al., "Preliminary Results of Full-Scale Pattern Measurements of Simple VHF Antennas in a Eucalyptus Grove," Special Technical Report 19, Contract DA 36-039 AMC-00040(E), SRI Project 4240, Stanford Research Institute, Menlo Park, California (January 1956).
- 4. N. K. Shrauger, et al., 'VHF Propagation Results for Low Antenna Heights in Tropical Forests," Special Technical Report 46, Contract DA 36-039 AMC-00040(E), SRI Project 4240, Stanford Research Institute, Menlo Park, California (in preparation).
- 5. Somchit Pongpangan and D. V. Vanek, "Environmental Description of Stanford Research Institute Test Site at Chumphon, Thailand," Joint Thai-U.S. Military Research and Development Center, Bangkok, Thailand (in preparation).
- H. W. Parker and Withan Makarabhiromya, "Electric Constants Measured in Vegetation and in Earth at Five Sites in Thailand," Special Technical Report 43, Contract DA 36-039 AMC-00040(E), SRI Project 4240, Stanford Research Institute, Menlo Park, California (December 1967).

დ

Security Classification						
DOCUMENT CONTR	ROL DATA - R &	D				
Security classification of title, body of abstract and indexing a	nnotation must be ei	intered where the a	overall report is classified)			
1 ORIGINATING ACTIVITY (Corporate author)		Za. REFORT SE Unclassi	CURITY CLASSIFICATION			
Stanford Research Institute			.Tieu			
Menlo Park, California 94025	N/A					
3 REPORT TITLE		-				
SELECTED EXAMPLES OF VHF SIGNAL PROPAGATIO	מכ					
RECORDS IN THREE TROPICAL TERRAINS						
RECORDS IN INCE INOPICAL LERRAINS						
4 DESCRIPTIVE NOTES (Type of report and inclusive dates)						
Special Technical Report 36						
5 AUTHOR(S) (First name, middle initial, last name)						
Nicholas K. Shrauger, Edwin M. Kreinber						
Manager, Edwin Mr. Michigel						
E REPORT OATE	78. TOTAL NO OF	PAGES	7b. NO OF REFS			
November 1967	45		6			
88. CONTRACT OR GRANT NO	90. ORIGINATOR'S	REPORT NUMB				
DA 36-039 AMC-00040(E)	Special T	echnical R	enort 36			
b. PROJECT NO	-	ial Technical Report 36				
SRI Project 4240						
Order No. 5384-PM-63-91 c. 98. OTHER REPORT NOIS! (Any other numbers that may be used)						
-"	this report)	er storm (Amy on	ner numbers mat may be assigned			
ARPA Order No. 371						
10 DISTRIBUTION STATEMENT						
Distribution of this document is unlimited.						
11 SUPPLEMENTARY NOTES	12 SPONSORING V	HEITARY ACTIV	/1T Y			
	Advanced	Research P	rojects Agency			
	Washingto		3 .			
		., 5.5.				
13 ARSTDACY						

Slow-speed chart records of received signal strength showing the perturbations caused by scattering from trees in the VHF band are presented. Data for several frequencies and polarization of transmitting and receiving antennas (simple dipoles and standard AN/PRC-25 manpack-set whips) are included, as well as a variety of combinations of clearings, jungle terrain, rubber plantations, and bamboo. The records permit a qualitative evaluation of the magnitude of signal fading that is

superimposed upon the smooth decrease of receive signals with distance between transmitter and receiver. Some similar results are presented for an AN/PRC-25

manpack system using AT-271/PRC antennas.

n	D	FORM	1473	(PAGE	1
u	טי	LNOVA	.14/3	,,,,,,,,	•

UNCLASSIFIED

Security Clausification LINK A LINK B LINK C KEY WORDS ROLE RCLE W 7 ROLE VHF Propagation Scutheast Asia Thailand Terrain Effect, Foliage Effects Foliage Mensuration Manpack Radios Xeledop Technique Signal Strength SEACORE

DD FORM . 1473 (BACK)

UNCLASSIFIED

Security Clessification